National Transportation Safety Board Washington, DC 20594

Brief of Accident

Adopted 10/26/1995

ΑT	L95	FAC)57

File No. 483	03/03/1995	GAINESVILLE, GA	Aircraft Reg No. I	N227DM	Т	ime (Local): 19:43 EST
Engine Make/Mo Aircraft Dama Number of Engin Operating Certificate Type of Flight Operat	e(s): None	n	Crew Pass	Fatal 2 0	Serious 0 0	Minor/None 0 0
Destinat	oint: SAVANNAH , GA ion: Same as Accident/Incide nity: Off Airport/Airstrip	ent Location		Weather Basic Lowe Wind Temper Obst	Weather: est Ceiling: Visibility:	Weather Observation Facility Instrument Conditions 200 Ft. AGL, Overcast 1.50 SM 090 / 005 Kts 7 Fog
Pilot-in-Command A	.ge: 46			Flight Ti	me (Hours)	
Certificate(s)/Rating(s) Airline Transport; Flight Instructionstrument Ratings Airplane; Helicopter	tor; Multi-engine Land; Single	-engine Land; Helicopter	Т	Las Total Ma	All Aircraft: at 90 Days: ake/Model: ment Time:	50 201

THE FLIGHT WAS EXECUTING THE NON-PRECISION NDB RWY 4 APPROACH, HAD REPORTED PROCEDURE TURN INBOUND, AND WAS CLEARED TO CHANGE TO ADVISORY FREQUENCY. WITNESSES OBSERVED THE AIRPLANE DESCEND OUT OF THE BASE OF THE OVERCAST CLOUDS IN A 10 DEG NOSE DOWN, 45 DEG LEFT WING DOWN ATTITUDE. THE AIRPLANE IMPACTED TERRAIN ABOUT 3/4 MI SSE OF THE AIRPORT. WITNESSES IN THE AREA REPORTED THAT THE WEATHER WAS CEILINGS OF ABOUT 100 FT AND VISIBILITY OF ABOUT 500 FT IN LIGHT RAIN AND FOG. THE MINIMUM DESCENT ALTITUDE FOR THE APPROACH IS 465 FEET AGL.

Brief of Accident (Continued)

ATL95FA057

File No. 483 03/03/1995 GAINESVILLE, GA Aircraft Reg No. N227DM Time (Local): 19:43 EST

Occurrence #1: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: APPROACH - FAF/OUTER MARKER TO THRESHOLD (IFR)

Findings

1. (F) WEATHER CONDITION - LOW CEILING

2. (F) WEATHER CONDITION - RAIN

3. (F) WEATHER CONDITION - FOG

4. (F) LIGHT CONDITION - DARK NIGHT

5. (C) MINIMUM DESCENT ALTITUDE - NOT MAINTAINED - PILOT IN COMMAND

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this accident as follows.

THE PILOTS FAILURE TO MAINTAIN THE MINIMUM DESCENT ALTITUDE DURING THE APPROACH. THE WEATHER AND DARK NIGHT LIGHT CONDITION WERE FACTORS.